# Work Order (Bid Form)

### WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

**CLIENT INFORMATION** 

Client Name:

Address:

Client ID:

Alt. Client ID: 16016SW-0512

AGENCY INFORMATION

Agency: SWHRA

Agency Phone: (731) 989-5111

Address: 1574 White AVE

Fax:

Henderson, TN

Email Address:

Agency Contact: STANFILL, BUTCH

Work Phone: Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

#### COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-234-2753

Client Name:

Work Order (Bid Form)

DOE Weatherization Assistant

Client ID:

Alt. Client ID: 16016SW-0512

Work Order Name

Version 8.5.0

Report Run On: 5/19/2010

## Measures

Measure 1 Seal Ducts				Componen	Inspected					
C	Comment							Actual		
				Estimated						
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Construction Materials/Hardwar e	Mastic Duct boots	Each	1						
2	Labor	Labor	Hour				Transaction of the	TO THE TAX		
(	Other Detail			***************************************	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		1 [	:		
L										
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									

1	Measure 2 Infilt	ration Redctn			Componen	ts		I	nspected
C	Comment								
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal all door jams, Bedroom 1 Seal wall to floor ceiling to wall and corners	Each	1	CONTRACTOR OF THE PROPERTY OF		Anna communication of the state	The state of the s	
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Hall bath seal pipes under sink,Seal baseboard Bath 2 seal water heater hatchSeal ceiling and floor and corners,Seal pipes under vanity	Each	1					
4	Labor	Labor	Hour						
5	Construction Materials/Hardwar e	Den seal all of closet,Seal return on inside,Seal all trim and hole at front door	Each	1					
6	Labor	Labor	Hour		The state of the s				- AM
7	Construction Materials/Hardwar e	Bedroom 2 Seal corners ceiling at door, Seal fireplace. Living room Seal trim at right side of wall	Each	1				Tax services	
8	Labor	Labor	Hour						
2	Other Detail			[			1		·····
	Measure Sub Total: Sub Tot							Sub Total:	
	Field Notes:								

Work Order Name: Report Run On: 5/19/2010

Measure 3 DW Comment			Component	ts		I.	nspecte	
Comment			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	Labor	Each	1					
Other Detail	- F	[	[					
		777						
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 4 Atti	c Ins. R-30			Componen	ts A2		I	nspecte
	c Ins. R-30							nspecte
Comment		Unita		Estimated		Ottv	Actual	
Comment # Material / Labor	Description / Comment	<i>Units</i>	Qty			Qty		nspecte 
Comment # Material / Labor		<i>Units</i> SqFt		Estimated		Qty	Actual	
Comment # Material / Labor 1 Insulation	Description / Comment  Attic Insulation - Blown		Qty	Estimated		Qty	Actual	
Comment  # Material / Labor  1 Insulation  2 Labor	Description / Comment  Attic Insulation - Blown Cellulose - R-30  Labor	SqFt	<b>Qty</b> 408	Estimated		Qty	Actual	
Comment  # Material / Labor  1 Insulation  2 Labor	Description / Comment  Attic Insulation - Blown Cellulose - R-30	SqFt SqFt	<b>Qty</b> 408	Estimated		Qty	Actual	Total
# Material / Labor Insulation Labor Miscellaneous Supplies	Description / Comment  Attic Insulation - Blown Cellulose - R-30  Labor  Repair roof leaks before	SqFt SqFt	<b>Qty</b> 408	Estimated		Qty	Actual	
# Material / Labor  1 Insulation  2 Labor  3 Miscellaneous Supplies	Description / Comment  Attic Insulation - Blown Cellulose - R-30  Labor  Repair roof leaks before insulating	SqFt SqFt Each	<b>Qty</b> 408	Estimated		Qty	Actual	
# Material / Labor  1 Insulation  2 Labor  3 Miscellaneous Supplies  4 Labor	Description / Comment  Attic Insulation - Blown Cellulose - R-30  Labor  Repair roof leaks before insulating	SqFt SqFt Each	<b>Qty</b> 408	Estimated		Qty	Actual	
# Material / Labor  1 Insulation  2 Labor  3 Miscellaneous Supplies  4 Labor	Description / Comment  Attic Insulation - Blown Cellulose - R-30  Labor  Repair roof leaks before insulating	SqFt SqFt Each	<b>Qty</b> 408	Estimated		Qty	Actual	

Client Name: Client ID: Work Order (Bid Form)
Vork Order Name:

DOE Weatherization Assistant

Alt. Client ID: 16016SW-0512

Report Run On: 5/19/2010

Measure 5 Att Comment	ic Ins. R-30			Componen	ts A1		ı	Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	1104	The state of the s				
2 Labor	Labor	SqFt	1104					
Other Detail	mg pra		,			<b>7</b>	·	
							And the state of t	
			Measur	e Sub Total:		] ;	Sub Total:	
Measure 6 Wa	Il Insulation			Componen  Estimated	ts E1,E2 W1,W		,N3,S1,	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1360				-	
2 Labor	Labor	SqFt	1360					
Other Detail								
						T T T T T T T T T T T T T T T T T T T		
				777				
			Measure	Sub Total:			Sub Total:	

Client Name:

Alt. Client ID: 16016SW-0512

Client ID: Work Order Name:

Work Order (Bid Form)

DOE Weatherization Assistant Version 8.5.0

Report Run On: 5/19/2010

	Measure 7 CO	Monitor is Needed			Componen		Inspected		
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1			TO STATE OF THE ST		
2	Labor	Labor	Hour	1					
(	Other Detail						~ ~		
				Measur	e Sub Total:			Sub Total:	
Con statements	Field Notes:				Macronia				
***************************************									
***************************************					The state of the s	t de decimination (Administration for APPENDENCE CONTRACT OF STATE			
			Work O	rder Gra	nd Total:		Gran	d Total:	

Report Run On: 5/19/2010

Page 6 of 6